



SITE NAME:	Davenport Dump
SITE NUMBER:	0000017
ADDRESS:	6965 Beech Grove Road
CITY:	Monrovia
COUNTY:	Morgan
SCORE:	28.20
SCORE DATE:	December 1990
CONTAMINANT TYPE:	Solvents
MEDIA AFFECTED:	Surface Water
CONTACT PERSON:	Ryan Groves at (317) 233-2406
LAST REVISED:	January 2003
SITE PHOTO	
<p>STATUS: The two-acre site operated from 1960 until January 1986. An inspection by IDEM personnel determined that the site was an unpermitted open dump containing domestic waste, auto parts, and drums of unknown contents. In 1986, IDEM removed the drums from the site. Samples were collected from the soil, surface water, sediment and residential wells. Of the all the samples taken, only two surface soil samples were found to be above action levels. The surface water appeared to have minimal impact, if any, from the open dump and the residential wells appeared to have no impact from the open dump. During the summer of 2001 additional buried drums were found at the site during a waste tire removal effort. The U.S. EPA conducted a site investigation in October of 2001. An immediate removal action was completed by the USEPA during the summer of 2002. IDEM mobilized to the site and completed the tire removal action during the fall of 2002. Site Cleanup activities are completed. The IDEM will seek to rescore and delist the site from the Commissioner's Bulletin during 2003.</p>	